

| | |
|------------------------|-----------------|
| Lead-Free Solder Paste | |
| 0769-38893080 | 0769-81360133 |
| lzd@dglzd.com | : 0769-38893080 |
| MSDS-1003 | 2018.12.1 |

| () | | | (CAS NO.) |
|---------------|-----------|----------|-------------------------|
| (Rosin) | --- | 3.6-5.4% | 8050-09-7 |
| (Solvent) | --- | 1.8-3.6% | 112-59-4 |
| (Additive) | --- | | --- |
| (tin) bismuth | Sn42 Bi58 | 85-90% | Sn7440-31-5 Bi7440-69-9 |
| --- | | | |

| |
|--|
| |
| |
| |
| |

| |
|--|
| |
| |
| |

| |
|--|
| |
| |
| |
| |

| | | | | |
|-------------------------|--------|-----------|-------------|-------------|
| | | | | |
| | | | | |
| (TWA) | (SGEL) | (Ceiling) | LD50 () | LC50 () |
| Sn:2.0mg/m ³ | ----- | ----- | ----- | ----- |



[Empty rectangular box]

[Empty rectangular box with faint text: , ,]

[Empty rectangular box]

| | | | |
|--------------------|--|--|--------------------|
| [Empty header row] | | | |
| | | | [Large empty cell] |
| | | | |
| | | | |
| | | | |